





VF 30...P (IEC)



A





N




V




P




INPUT




P56 B14




OUTPUT




X








VF 30...P (IEC)


F₋




U



INPUT



OUTPUT



		M	M1	M2	N	N1	N2	N3	N4	
VF 30	P56 B5	9	10.4	3	120	100	80	7	7	1.1
VF 30	P56 B14	9	10.4	3	80	65	50	7	5.5	
VF 30	P63 B5	11	12.8	4	140	115	95	8	9.5	
VF 30	P63 B14	11	12.8	4	90	75	60	6	5.5	